

Weaving Cast On Checklist

☐

Cam Lever to PLAIN KNITTING (Not weaving) 

☐

Pull working needles to "D" position

☐

Pass the carriage left then right (no yarn)

☐

Pull every-other-needle to "D"

☐

Thread the carriage

☐

Engage weaving brushes

☐

Pass the working yarn OVER the needles and hold

☐

Knit left – Knit right

☐

Dis-engage the weaving brushes

☐

Continue Knitting

☐

Hang weights

